

## Que hacer para cambiar la IP en la impresora 2C-POS80-02\_Series

**1**.- Después de instalar la impresora con el driver del sistema operativo que estemos usando, procedemos a ejecutar la utilidad "**Testing Tool V6.2.exe**"

a) Luego seguimos los pasos según nos los indican la siguientes gráficas.

Testing Tool V6.2		×
	·	
	$\begin{pmatrix} 1 \end{pmatrix}$	
Show Receive Data	Save Receive Data	<u></u>
Pause Clear LIEX	Show Path: C:\Users\Juan Tomas\D\Testing Tool V6.2\ Modify Save	1
	Multiple: NO 9100 Auto Send Help More	
USB1 V	IP Address: 192 . 168 . 1 . 117 T= 1000 MS	
Baud Rat Ethernet	HEX Send Send NewLine ChineseMode	
Check: NONE ~	1b 09 1b 64 00 1b 15	
Data Bit: 8 🗸 🗸	Open	
Stop Bit: 1 V	Port V Clear	
Flow Control: NONE V	Send File	
DTR RTS	Path: No File Selected. Auto Send Browse Send	
-)H	Port closed. RX:0 TX:0 ReCount	:

Testing Tool V6.2	×
	<u>^</u>
	× .
Show Receive Data	Save Receive Data
Pause Clear HEX Show	Path: C:\Users\Juan Tomas\D\Testing Tool V6.2\ Modify Save
Port: USB1 $\sim$ Mult	tiple: NO ~ 9100 ~ Auto Send Help More
IP Ad	dress: 192 . 168 . 1 . 117 T= 1000 MS Print Test
	HEX Send Send NewLine ChineseMode
Check: NONE V	Cond
Data Bit: 8  Close	
Stop Bit: 1 V Port	Clear
Flow Control: NONE  Send	File
DTR RTS Path:	No File Selected. Auto Send Browse Send
-🛏 USB1 O	PENED. RX:0 TX:0 ReCount



Testing Tool V6.2	×
	3
Show Receive Data     Pause   Clear   HEX Signature	Save Receive Data       how       Path:       C:\Use s\Juan Tomas\D\Testing Tool V6.2\       Modify
Port: USB1 ~	Multiple: NO ~ 9100 ~ Auto Send Help More
Baud Rate: 9600 ~ Check: NONE ~	IP Address.     192     108     1     117     1     1000     INS     Print     Print     est       Ib     HEX Send     Send NewLine     ChineseMode     Image: ChineseMode     I
Data Bit: 8 $\checkmark$ Stop Bit: 1 $\checkmark$	Close Port 4 Send Clear
Flow Control:     NONE       DTR     RTS	Send File Path: No File Selected. Auto Send Browse Send
-🛱 US	B1 OPENED. RX:0 TX:0 ReCount

2.- Luego ejecutamos el utilitario general para cambio de parámetros de las impresoras series 2C-POS80-02, el utilitario, "Testing Tool V6.2.exe"

BOC Brinter	( )	)					
2C-POS80-02 Series							
		Printer Type: 20-0	00580-02	~			
			0000 02				
	Port	Sorial Bor	t Parameters	Printe	er Setup	Bluetoot	h
		Senarro	c Parameters	Drint Direction	Not Cot		
	IP Address	Baud Rate:	~	Print Direction:	Not Set V	Bluetooth Open: off	~
		Verify:	$\sim$	Print Speed:	Not Set 🗸 🗸	Enable Bluetooth Passwo	rd: not set 🗸
	Printer Current Serial Portiettings	Data Bits:		RePrint After Lack Paper:	Not set 🗸 🗸	Bluetooth Name: not s	e. ~
	IP AddresBaud Rate: 9600	Flow Control:	~	Cutter Enable:	Not Set $\sim$	Bluetooth Password: not	e v
	Gateway: Verify:_ NONE	Error Handding:	~	Paper Will Do:	Not Set $\sim$	Ruotooth Typo:	
	Data Bits: 8	Error Harnung.		Voice:	Not Set 🛛 🗸	Bidecooch Type: not s	e. ~
	Flow control: RTS/CTS		Not Cot			3G	
	Bitmap Option	Language:	Not Set			Heartbeat interval: not	50° V
		Code Page:	NOT SET V				+ pot set v
		Font:	Not Set 🗸 🗸	Manufacturer: Not Se $\sim$		Cloud print IP address po	IT: HOUSEL V
		Paper Sensor:	Not Set 🛛 🗸	Printer Type: Not Se 🗸		192.168.1.114	Port: 10
		Print Density:	Not Set 🛛 🗸	Factory Date: Not Se V	6/ 8/2021 ~	Device ID: not se $\sim$	
		Instruction Set:	Not Set 🗸	ractory bate. Not be -	0/ 0/2021 -		
		0D Instruction:	Not Set			WIFI	
		Delet Midthe	Not Oct		Cat	Network Connection Para	meters: not se
		Print Width:	NOT SET V	Derault Settings	Set	protocol: TCP $\lor$	
	Save position: 1ct Resures	Buzzer:	Not set ~			CS: Client $\checkmark$	
	Download Print	Black Mark Check:	Not Set 🛛 🗸	Print Te	st	IP:	Port:
		Bill Test:	No Set 🛛 🗸			AP Parameters: not se $\sim$	
		print paperWidth:	No Set 🗸 🗸			AP Name:	Key:



3.-En este punto en la gráfica de arriba al pulsar tomamos la opción "**NET**" y luego pasamos a dar los pasos de la siguiente pantalla.







## 4) En la próxima grafica vemos como cambiamos los datos correspondientes a la nueva IP

🙉 s	etting Tool V3.5845							_	
	POS Printer								H
	2C-POS80-02 Series			_		9	)		
				Printer Type: 2C-P	POS80-02				
		Port Dert Types NET	<b>T</b>	Corial Bort	Barmatar	Print	er Setup	Bluetooth	
		TD Address	· ·	Baud Bater	Parameter	Print Direction:	Not Set 🗸		
		192 . 168 .	1 . 114	Baud Rate:		Print Speed:	Not Set V	Bluetooth Open: off	$\sim$
		Network port parameter set	ttings	Verify:	~	RePrint After Lack Paper:	Not set ~	Enable Bluetooth Password: not	ot set $\smallsetminus$
		IP Address: 192 . 168 .	. 1 . 118	Data Bits:	~	Cutter Enable:	Not Set 🗸 🗸	Bluetooth Name: not se ~	
		Subnet Mask: 255 . 255 . Gateway: 102 168	. 255 . 0	Flow Control:	· · · · · · · · · · · · · · · · · · ·	Paper Will Do:	Not Set $\sim$	Bluetooth Password: not	
		MAC Address: 88 26 23	F1 - ED - DF	Error Hanidling:	~	Voice:	Not Set 🛛 🗸	Bluetooth Type: not se v	
		Get Param Random	n MAC Set	Language:	Not Set 🗸	,		3G	
		Bitmap Option		Code Page:	Not Set 🛛 🗸	-		Heartbeat interval: not se $ \smallsetminus $	
				Font:	Not Set 🗸 🗸	Manufacturers Net Court		Cloud print IP address port: not	set 🗸
				Paper Sensor:	Not Set 🗸	Bristor Type: Not Sc V		192.168.1.114 Port:	: 10
				Print Density:	Not Set 🗸	Factory Data: Not Sc	6/ 8/2021	Device ID: not se v	
				Instruction Set:	Not Set 🗸 🗸	Actory Date: Not be	5/ 5/2021 V		
				0D Instruction:	Not Set 🗸	•		WIFI	
				Print Width:	Not Set 🗸 🗸	Default Settings	Set	Network Connection Parameters:	not ser 🗸
				Buzzer:	Not set 🗸 🗸	·		CS: Client V	
		Save position: 1st	✓ Browse	Black Mark Check:	Not Set 🗸 🗸	Print Te	est	IP: Po	ort:
		Download	Print	Bill Test:	No Set 🗸 🗸	·		AP Parameters: not se v	
				print paperWidth:	No Set 🗸 🗸	•		AP Name: Key:	
51	En la siguient	te pantalla ver	mos con	no queda	a ejecuta	ado el cambi	o de la r	nueva IP	11
5 I	En la siguient	e pantalla ver	mos con	no queda	a ejecuta	ado el cambi	o de la r	nueva IP	11
5 1 ing Tool V3.5843 205 Printer 2C-POS80-02 Sena	En la siguient	te pantalla ver	mos com	no queda	a ejecuta	ado el cambi	o de la r	nueva IP	
51 ing Tool V3.5845 205 Printer 205 20580-02 Series	En la siguient	e pantalla ver	Printer Type:	no queda	a ejecuta	ado el cambi	o de la r	nueva IP	11
51 ing Tool V3.5845 205 Printer 205 Pointer 205 20580-02 Senter	En la siguient	te pantalla ver	Printer Type:	2C-POS80-02 Port Parameters	a ejecuta	ado el cambi	o de la r	nueva IP –	
51	En la siguient	te pantalla ver	Printer Type:	2C-POS80-02 Port Parameters	a ejecuta	ado el cambi Printer Set Print Direction: Not	o de la r	nueva IP – Bluetooth	
5 1 ing Tool V3.5845 205 Printer 20: 20: 20: 20: 20: 20: 20: 20: 20: 20:	En la siguient	Ype: NET  168 . 1 . 114	Printer Type: Serial Baud Ra	2C-POS80-02 Port Parameters ate:	a ejecuta	Printer Set Print Direction: Not Print Speed: Not	o de la r	Bluetooth Open: off	
51	En la siguient	ype: NET . 168 . 1 . 114 veter settings	Printer Type: Serial Baud Ra Ve Data 6	2C-POS80-02 Port Parameters ate:	a ejecuta	Printer Set Print Direction: Not Print Speed: Not t After Lack Paper: Not	o de la r	Bluetooth Bluetooth Bluetooth Open: off Enable Bluetooth Password: nr	11
5 1 ing Tool V3.5843 205 Printer 2.2C-PO580-02 Series	En la siguient	ype: NET . 168 . 1 . 114 veter settings 2 168 . 1 . 118	Printer Type: Serial Baud Ra Ve Data E	2C-POS80-02 Port Parameters ate: rify: sits:	a ejecuta	Printer Set Print Direction: Not Print Speed: Not t After Lack Paper: No Cutter Enable: Not	o de la r	Bluetooth Open: off Bluetooth Password: nr Bluetooth Name: not se v	11
51 ing Tool V3.5843 205 Printer 2 2C-POS80-02 Senia	En la siguient	Ype:       NET         . 168       1         . 168       1         . 168       1         . 168       1         . 12       1.08	Printer Type: Printer Type: Serial Baud Ra Ve Data B Flow Cont Error prompt	2C-POS80-02 Port Parameters ate: rify: 3lts: trol:	a ejecuta	Printer Set Print Direction: Not Print Speed: Not t After Lack Paper: Not Cutter Enable: Not Paper Will Do: Not	o de la r	Bluetooth Open: off Bluetooth Password: not Bluetooth Password: not	111
51 ing Tool V3.5845 205 Printer 2 2C-PO580-02 Sents	En la siguient Por Port T IP Address: 19 Subnet Mask: 22 Gateway: 11 MAC Address: 88	ype:       NET         . 168       1         . 168       1         . 168       1         . 152       . 255         . 2       . 188         . 2       . 198         . 12       . 198	Printer Type: Serial Baud Ra Ve Data E Flow Coni Erro prompt	2C-POS80-02 Port Parameters ate: rify: 3its: trol:	a ejecuta	Printer Set Print Direction: Not Print Speed: Not t After Lack Paper: Not Cutter Enable: Not Paper WirDo: Not Voice: Not	o de la r	Bluetooth Password: not se Bluetooth Type: not se	111
51 ing Tool V3.5845 POS Printer 2.C.POS80-02 Series	En la siguient Port T IP Address IP Address: 22 Gateway: 15 MAC Address: 88 Get Param	ype:       NET         . 168       1         . 168       1         . 168       1         . 168       1         . 168       1         . 168       1         . 168       1         . 168       1         . 168       1         . 168       1         . 168       1         . 168       1         . 168       1         . 168       1         . 168       1         . 168       1         . 168       1         . 20       .25         . 21       .68         . 1       1         . 26       .23         . 168       1         . 1       1         . 26       .23         . 27       .68	Printer Type: Printer Type: Baud Ra Baud Ra Ve Data E Flow Com Erro Prompt Set n	2C-POS80-02 Port Parameters ate: iffy: 3its: trol:	a ejecuta	Printer Set Print Direction: Not Print Speed: Not t After Lack Paper: Not Cutter Enable: Not Paper Wir Do: Not Voice: Not	o de la r	Bluetooth Password: not se Bluetooth Password: not se Bluetooth Type: not se Bluetooth Type: not se 36	11 v
51	En la siguient Port Port T IP Address IP Address: 19 Subnet Mask: 25 Gateway: 15 MAC Address: 88 Get Param Bitmap Option	ype:       NET         . 168 . 1 114         veter settings         2       168 . 1 118         5	Printer Type: Serial Baud Ra Ve Data E Flow Cont Erro prompt Set n	2C-POS80-02 Port Parameters ate: rnfy: 3lts: trol: t tetwork port parameters	a ejecuta	Printer Set Print Direction: Not Print Speed: Not t After Lack Paper: Not Cutter Enable: Not Paper WirDo: Not Voice: Not	o de la r	Bluetooth Open: off Bluetooth Open: off Enable Bluetooth Password: no Bluetooth Name: not se Bluetooth Password: not se Bluetooth Type: not se 36 Heartbeat interval: not se	
51	En la siguient Port Port T IP Address PAddress: 19 Subnet Mask: 25 Gateway: 19 MAC Address: 18 Get Param Bitmap Option	Ype:       NET         168       1         168       1         168       1         168       1         111         Seter settings         2       168         168       1         12       168         12       168         12       168         12       168         12       168         12       168         168       1         126       1         126       12         126       12         126       12         126       12         126       12         126       12         126       12         126       12         12       12         12       12         12       12         13       12         14       12         14       12         14       12         14       12         14       12         15       12         14       12         15       12      <	Printer Type: Serial Baud Ra Ve Data E Flow Coni Erro prompt	2C-POS80-02 Port Parameters ate: rify: ate: tetwork port parameters	RePrint	Printer Set Print Direction: Not Print Speed: Not t After Lack Paper: Not Cutter Enable: Not Paper WirDo: Not Voice: Not	o de la r	Bluetooth Open: off Bluetooth Password: no Bluetooth Password: no Bluetooth Name: not se Bluetooth Name: not se Bluetooth Type: not se Bluetooth Type: not se Cloud print IP address port: not	11 
51	En la siguient	Ype:       NET         . 168       1       . 114         Seter settings       2       . 168       1       . 118         168       . 1       . 118       . 126       . 255       . 0       . 168       1       . 1         2       . 168       1       . 118       . 126       . 23       . 168       . 1       . 1         2       . 168       . 1       . 118	Printer Type: Printer Type: Serial Baud Ra Ve Data E Flow Comi Erro prompi Set n Pa	2C-POS80-02 Port Parameters ate: rnfy: ate: t t t t t t t t t t t t t t t t t t	RePrint	Printer Set Print Direction: Not Print Speed: Not t After Lack Paper: Not Cutter Enable: Not Paper W/DO: Not Voice: Not cturer: Not Se v Type: Not Se v	o de la r	Bluetooth Bluetooth Bluetooth Open: off Enable Bluetooth Password: in Bluetooth Name: not se Bluetooth Password: not se Bluetooth Type: not se Bluetooth Type: not se Cloud print IP address port: not 192.168.1.114 Port	11 
51	En la siguient	Ype:       NET         168       1         168       1         168       1         114         Seter settings         2       168         168       1         2       168         168       1         2       168         1       1         26       23         FI       1         26       23         FI       1         Set       Set	Printer Type: Printer Type: Serial Baud Ra Ve Data E Flow Comi Erre prompt Set n Pa Pa Print Dens	2C-POS80-02 Port Parameters ate: trify: tetwork port parameters sty: Not Set	RePrint	Printer Set Print Direction: Not Print Speed: Not t After Lack Paper: Not Cutter Enable: Not Paper Wir Do: Not Voice: Not cturer: Not Se ✓ Type: Not Se ✓ Date: Not Se ✓	o de la r	Bluetooth Open: off Bluetooth Open: off Bluetooth Password: nr Bluetooth Password: nr Bluetooth Password: not se v Bluetooth Type: not se v Bluetooth Type: not se v Cloud print IP address port: not 192 . 168 . 1 . 114 Port Device ID: not se v	111 
51	En la siguient	Ype:       NET         . 168       1       . 114         Seter settings       . 168       1         2       168       1       . 118         5       . 225       . 0       . 1         2       168       1       . 1         26       2.3       F1       ED         2.68       1       . 1       . 1         26       2.3       F1       ED         Random MAC       Set       . Set	Printer Type: Printer Type: Serial Baud Ra Ve Data E Flow Comi Erro prompi Set n Pa Print Dens Instruction S	2C-POS80-02 Port Parameters ate: ify: attroi: t etwork port parameters sity: Not Set iet: Not Set	RePrint Success!	Printer Set Print Direction: Not Print Speed: Not t After Lack Paper: Not Cutter Enable: Not Paper Wir Do: Not Voice: Not turer: Not Se v Type: Not Se v Date: Not Se v 6/ 8	o de la r	Bluetooth Open: off Bluetooth Open: off Bluetooth Password: nr Bluetooth Name: not se v Bluetooth Password: not se v Bluetooth Type: not se v Bluetooth Type: not se v Gloud print IP address port: not 192, 168, 1, 1114 Port Device ID: not se v	11 
51	En la siguient	Ype: NET . 168 . 1 . 114 Yeter settings 2 168 . 1 . 114 Yeter settings 2 168 . 1 . 118 15 . 215 . 0 2 . 168 1 . 118 16 . 1 . 118 17 . 100 DF Random MAC Set	Printer Type: Printer Type: Serial Baud Ra Ve Data B Flow Comp Set n Pal Print Dens Instruction S OD Instruct	2C-POS80-02 Port Parameters ate: rrify: ats: t hetwork port parameters sity: Not Set ion: Not Set	RePrint	Printer Set Print Direction: Not Print Speed: Not Cutter Enable: Not Cutter Enable: Not Voice: Not Cutter:: Not Se  Type: Not Se  Date: Not Se  6/ 8	o de la r	Bluetooth Bluetooth Bluetooth Open: off Enable Bluetooth Password: nr Bluetooth Name: not se v Bluetooth Name: not se v Bluetooth Password: not se v Bluetooth Type: not se v Gloud print IP address port: not 192.168.1.114 Port Device ID: not se v WIFI	11 
51	En la siguient	ype: NET . 168 . 1 . 114 veter settings 2 . 168 . 1 . 114 veter settings 2 . 168 . 1 . 118 5 . 225 . 255 . 0 2 . 168 . 1 . 118 5 . 225 . 255 . 0 2 . 168 . 1 . 128 Random MAC Set	Printer Type: Printer Type: Serial Baud Ra Ve Data E Flow Comp From promp! Set n Pal Print Dens Instruction S OD Instruct Print Wik	2C-POS80-02 Port Parameters ate: infy: ats: t betwork port parameters sty: Not Set ion: Not Set t t: Not Set t	RePrint	Printer Set Print Direction: Not Print Speed: Not Cutter Enable: Not Cutter Enable: Not Cutter Enable: Not Voice: Not Cutter: Not Se  Type: Not Se  Date: Not Se  efault Settings	o de la r	Bluetooth Bluetooth Bluetooth Open: off Enable Bluetooth Password: nr Bluetooth Name: not se Bluetooth Name: not se Bluetooth Password: not se Bluetooth Password: not se Bluetooth Password: not se Cloud print IP address port: not 192 . 168 . 1 . 114 Port Device ID: not se WIFI Vetwork Connection parameters: paratorot. Trans	11 
51	En la siguient	ype:       NET         , 168       1         , 168       1         , 168       1         , 168       1         , 168       1         , 168       1         , 168       1         , 168       1         , 168       1         , 168       1         , 168       1         , 168       1         , 168       1         , 168       1         , 168       1         , 168       1         , 168       1         , 2       168         , 168       1         , 2       168         , 168       1         , 2       168         , 2       168         , 168       1         , 2       168         , 168       1         , 2       168         , 168       1         , 2       168         , 170       1         , 26       23         , 170       1         , 170       1         , 170       1         , 170 <t< td=""><td>Printer Type: Printer Type: Serial Baud Ra Ve Data B Flow Cont Erro prompi Set n Pa Print Dens Instruction S OD Instruct Print Wik Buz</td><td>2C-POS80-02 2C-POS80-02 Port Parameters ate: infy: ats: ats: sty: Not Set int: Not Set it: Not Set it:</td><td>RePrint</td><td>Printer Set Print Direction: Not Print Direction: Not Print Speed: Not t After Lack Paper: Not Cutter Enable: Not Paper Wir Do: Not Voice: Not turer: Not Se Type: Not Se Date: Not Se 6/ 8 eefault Settings</td><td>o de la r</td><td>Bluetooth Bluetooth Bluetooth Open: off Enable Bluetooth Password: nr Bluetooth Name: not se v Bluetooth Password: not se v Bluetooth Password: not se v Bluetooth Type: not se v Gloud print IP address port: not 192 . 168 . 1 . 114 Port Device ID: not se v WIFI Vetwork Connection Parameters: protocol: TCP v C; Client v</td><td>11 </td></t<>	Printer Type: Printer Type: Serial Baud Ra Ve Data B Flow Cont Erro prompi Set n Pa Print Dens Instruction S OD Instruct Print Wik Buz	2C-POS80-02 2C-POS80-02 Port Parameters ate: infy: ats: ats: sty: Not Set int: Not Set it:	RePrint	Printer Set Print Direction: Not Print Direction: Not Print Speed: Not t After Lack Paper: Not Cutter Enable: Not Paper Wir Do: Not Voice: Not turer: Not Se Type: Not Se Date: Not Se 6/ 8 eefault Settings	o de la r	Bluetooth Bluetooth Bluetooth Open: off Enable Bluetooth Password: nr Bluetooth Name: not se v Bluetooth Password: not se v Bluetooth Password: not se v Bluetooth Type: not se v Gloud print IP address port: not 192 . 168 . 1 . 114 Port Device ID: not se v WIFI Vetwork Connection Parameters: protocol: TCP v C; Client v	11 
51	En la siguient	te pantalla ver	Printer Type: Printer Type: Serial Baud Ra Ve Data B Flow Cont Erro prompi Set n Pa Print Dens Instruction S OD Instruct Print Wk Buz Black Mark Ch	2C-POS80-02 2C-POS80-02 Port Parameters ate: infy: ats: infit: int etwork port parar it int int int int int int int int int	ejecuta	Printer Set	o de la r	Bluetooth Bluetooth Bluetooth Open: off Enable Bluetooth Password: on Bluetooth Name: not se v Bluetooth Name: not se v Bluetooth Password: not se v Bluetooth Password: not se v Gloud print IP address port: not 192 . 168 . 1 .114 Port Device ID: not se v WIFI Vetwork Connection Parameters: protocol: TCP v CS: Client v	11
51	En la siguient	Ype:       NET         168       1         168       1         168       1         114         veter settings         2       168         168       1         168       1         168       1         168       1         168       1         168       1         168       1         168       1         168       1         12       168         168       1         12       16         12       16         12       16         12       16         13       1         12       16         14       1         12       16         14       1         15       1         16       1         17       16         18       1         16       1         17       16         18       1         17       16         18       16         19       16         10	Printer Type: Printer Type: Baud Ra Ve Data B Flow Coni Erro prompi Set n Pa Print Dens Instruction S OD Instruct Print Wik Buz Black Mark Chh	2C-POS80-02 Port Parameters ate: Infly: Infl	a ejecuta	Printer Set	o de la r	Bluetooth Bluetooth Bluetooth Open: off Enable Bluetooth Password: off Bluetooth Name: not se v Bluetooth Name: not se v Bluetooth Password: not v Bluetooth Password: not v Bluetooth Password: not se v Cloud print IP address port: not se v Bluetooth Password: not se v Bluetoot	11